


MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 14, Township 9 North, Range 1 West,


Monument Description & Remarks: 0.2'x0.7' Stone Found flush with ground. Stone is half Limestone and half Sandstone. Survey Marker and post found on NE side of stone.



COMPLETED BY *Shu U. Tanker*

I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 27th day of December, 2004 A.D.

Ben E. Bledsoe
 Indiana Registered Land Surveyor No. S0559



MONUMENT RECORD

Corner I.D. #


U-11

STATE OF INDIANA - COUNTY OF MONROE

Section Fourteen (14), Township 9 North, Range 1 West

Monument Description & Remarks: Found Stone at East 1/4 corner; no "X".
Stone is 0.2' x 0.7' x 0.3' out of ground. Stone is part limestone & part
fieldstone. Chisled 1 side of a "X" . . . see note. Survey marker sign
and post set.

Recovery Tie Drawing



State of Indiana
County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; and the above data is given under my hand and seal this 20th day of April, 1995 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Office of Monroe County Surveyor
United States Government Agency

Monroe County Surveyor
Title

Field Book:

95-01

Page:

30